

PPE & Tool List for Testing

Mandatory PPE

8" high CSA approved steel toed work boots

Clear (No Tint) CSA approved safety glasses

Welding coat, and welding gloves

Nonflammable clothing

Welding helmet and cap

Suggested Tools

Chipping hammer

Wire brush

Half round 14" coarse bastard file

Mig pliers

Locking pliers

Combination square

Measuring tape

Adjustable wrench

Angle grinder